

Layer: ana_snirh_adutora_es_epsg_31984
Type: GeoJSON

```

{
  "crs": {
    "properties": {
      "name": "urn:ogc:def:crs:EPSG::31984"
    },
    "type": "name"
  },
  "features": [
    {
      "geometry": {
        "coordinates": [
          [
            [
              341881.44862538,
              7746552.93798278
            ],
            [
              341997.51763056,
              7746199.86012925
            ],
            [
              342080.63313145,
              7745903.06020873
            ],
            [
              342187.49502704,
              7745475.62020282
            ],
            [
              342246.76842006,
              7745261.83411363
            ],
            [
              342413.02890102,
              7745060.00030525
            ],
            [
              343018.64587242,
              7744858.09548884
            ],
            [
              343339.22846162,
              7744775.01241256
            ],
            [
              343659.81250956,
              7744703.75999602
            ]
          ]
        ],
        "type": "MultiLineString"
      },
      "geometry_name": "the_geom",
      "id": "ana_snirh_adutora_es_epsg_31984.1",
      "properties": {
        "ADUTORA": "SIS - Viana",
        "ESTADO": "ES",
        "SITUAA": "Sistema Existente",
        "fid": 1
      },
      "type": "Feature"
    },
    {
      "geometry": {
        "coordinates": [
          [
            [
              345856.46949019,
              7757705.7839571
            ],
            [
              347138.90816097,
              7758038.21254551
            ],
            [
              349252.46401923,
              7758489.40066052
            ],
            [
              351389.77116821,
              7758655.70050656
            ]
          ]
        ]
      }
    }
  ]
}

```

```
    ],
    "type": "MultiLineString"
  },
  "geometry_name": "the_geom",
  "id": "ana_snirh_adutora_es_epsg_31984.2",
  "properties": {
    "ADUTORA": "SIS - Duas Bocas",
    "ESTADO": "ES",
    "SITUAA": "Sistema Existente",
    "fid": 2
  },
  "type": "Feature"
},
{
  "geometry": {
    "coordinates": [
      [
        [
          378509.90903285,
          7786511.99895497
        ],
        [
          377749.9746659,
          7785371.98427473
        ],
        [
          376325.09443982,
          7784612.08507887
        ],
        [
          374330.14838823,
          7783472.20077007
        ],
        [
          373760.29586424,
          7781762.32720402
        ],
        [
          374710.16321016,
          7780717.4339049
        ],
        [
          375090.17212874,
          7778912.67319219
        ],
        [
          375660.05878856,
          7777582.7691694
        ],
        [
          375945.03271284,
          7775682.88857644
        ],
        [
          375660.0622799,
          7772928.1103464
        ],
        [
          375367.40733225,
          7770820.54340555
        ],
        [
          367485.18861856,
          7766603.72644592
        ],
        [
          367477.93059985,
          7766623.04714446
        ],
        [
          366675.95568366,
          7768694.87203897
        ],
        [
          365673.4482049,
          7772370.46901179
        ],
        [
          365687.5509658,
          7773858.35337816
        ],
        [
          365011.88222549,
```

```
7774519.58853506
],
[
  363959.11242507,
  7774416.20434872
],
[
  363279.02995945,
  7773706.32245171
]
],
[
  [
    363802.23481425,
    7757200.03496071
  ],
  [
    366341.77328298,
    7758937.59976307
  ],
  [
    368213.0688164,
    7759806.38797042
  ],
  [
    368814.48656309,
    7763081.07522962
  ],
  [
    367485.18861856,
    7766603.72644592
  ],
  [
    366709.32418975,
    7766188.66596728
  ]
],
[
  [
    366725.67336841,
    7766166.21751544
  ],
  [
    365197.87300627,
    7766273.39282813
  ],
  [
    360158.79628199,
    7766139.39471821
  ],
  [
    358845.40951315,
    7766434.25758964
  ],
  [
    355977.39102371,
    7767988.85249154
  ],
  [
    355414.50095088,
    7767908.45606826
  ],
  [
    355066.02520082,
    7767559.95817173
  ],
  [
    355628.86925828,
    7766916.63902515
  ],
  [
    356459.86378435,
    7766166.16787258
  ],
  [
    359976.29346662,
    7763030.98446533
  ]
],
[
  [
    358171.81375935,
    7764601.43008576
```

```

    ],
    [
      356801.85666333,
      7762329.2265343
    ],
    [
      356033.28551837,
      7761427.10515419
    ]
  ]
],
"type": "MultiLineString"
},
"geometry_name": "the_geom",
"id": "ana_snirh_adutora_es_epsg_31984.3",
"properties": {
  "ADUTORA": "SIN - Santa Maria",
  "ESTADO": "ES",
  "SITUAA": "Sistema Existente",
  "fid": 3
},
"type": "Feature"
},
{
  "geometry": {
    "coordinates": [
      [
        [
          357397.54684737,
          7744297.07853186
        ],
        [
          358522.70777034,
          7744268.42774654
        ],
        [
          359424.87855389,
          7744067.95493441
        ],
        [
          359692.23797409,
          7742898.43124049
        ],
        [
          359458.31106712,
          7740459.10488606
        ],
        [
          359992.91631789,
          7738721.56643913
        ],
        [
          360059.84979165,
          7737886.13789709
        ],
        [
          359391.42452366,
          7736248.87521079
        ],
        [
          358856.82522733,
          7734611.46637232
        ],
        [
          358388.99275994,
          7733742.71507443
        ],
        [
          358021.48846146,
          7732907.3206591
        ],
        [
          357787.52241434,
          7731871.46171803
        ],
        [
          357486.81117513,
          7731036.05848879
        ],
        [
          357018.98909177,
          7730200.78998826
        ]
      ]
    ]
  }
},

```

```
[
  356450.94324297,
  7729432.1986404
],
[
  355782.70673033,
  7728496.56426164
],
[
  354813.6205426,
  7727427.27028341
]
],
[
  [
    354342.37523677,
    7752040.60090759
  ],
  [
    355530.39212788,
    7751765.12921753
  ],
  [
    357138.20308933,
    7751412.91797535
  ],
  [
    358221.94852337,
    7750750.94804853
  ],
  [
    358225.7383351,
    7750710.69052971
  ],
  [
    358422.4694014,
    7748578.97949539
  ],
  [
    357892.61927498,
    7747343.1156815
  ],
  [
    356944.67068445,
    7745648.79357427
  ],
  [
    356944.70253681,
    7745144.56161988
  ],
  [
    357146.43238659,
    7744559.66829336
  ],
  [
    358013.6895127,
    7743651.95577658
  ]
],
[
  [
    354229.50805044,
    7752064.89130778
  ],
  [
    349223.40415979,
    7747051.69167098
  ]
],
[
  [
    354329.74742409,
    7752138.01930517
  ],
  [
    354155.44793998,
    7754632.42668433
  ]
],
[
  [
    358216.77556373,
    7750708.17589023
  ]
]
```

```
],
[
  358225.7383351,
  7750710.69052971
],
[
  360171.72715245,
  7751279.862702
],
[
  360428.48808323,
  7751355.0016907
]
],
[
  [
    360441.17420832,
    7751361.96872565
  ],
  [
    363335.7193957,
    7751831.73877744
  ]
]
],
[
  [
    360428.37854532,
    7751368.51003099
  ],
  [
    362243.04821321,
    7750317.25817969
  ],
  [
    363742.7054955,
    7749448.41663385
  ]
]
],
[
  [
    360157.00382874,
    7751241.44716154
  ],
  [
    362309.6120801,
    7746854.95047275
  ]
]
],
[
  [
    362241.6473442,
    7750346.69595521
  ],
  [
    362243.04821321,
    7750317.25817969
  ]
]
],
[
  [
    354432.74334265,
    7752071.92082784
  ],
  [
    358438.03336836,
    7751761.93653062
  ],
  [
    359303.00924636,
    7753258.42604635
  ],
  [
    359326.8823671,
    7753299.6864451
  ]
]
],
[
  [
    360173.63981632,
    7751275.7836467
  ],
  [
    360171.72715245,
```

```

    7751279.862702
  ],
  [
    359311.89813326,
    7753141.27956632
  ],
  [
    359301.79342768,
    7753163.33372328
  ]
],
[
  [
    359301.57517189,
    7753217.67749501
  ],
  [
    359303.00924636,
    7753258.42604635
  ],
  [
    359325.4591671,
    7753897.65519401
  ],
  [
    359323.53322364,
    7754658.77553399
  ],
  [
    359830.44460059,
    7755972.30342482
  ],
  [
    360084.78948626,
    7756303.01994987
  ]
],
[
  [
    359250.74608506,
    7753135.24087168
  ],
  [
    359311.89813326,
    7753141.27956632
  ],
  [
    363280.05300064,
    7753531.31661937
  ],
  [
    364067.98805252,
    7754768.00833124
  ]
]
],
  "type": "MultiLineString"
},
"geometry_name": "the_geom",
"id": "ana_snirh_adutora_es_epsg_31984.4",
"properties": {
  "ADUTORA": "SIN - Juc\u00c3\u00ba",
  "ESTADO": "ES",
  "SITUAA": "Sistema Existente",
  "fid": 4
},
"type": "Feature"
},
{
  "geometry": {
    "coordinates": [
      [
        324467.0726849,
        7741922.69946417
      ],
      [
        324625.25134694,
        7742478.32715802
      ],
      [
        324851.08003145,
        7742839.11684192
      ]
    ]
  }
}

```

```
    ],
    [
      325207.68152813,
      7743233.79911497
    ],
    [
      325718.48571326,
      7744575.18490456
    ],
    [
      326424.24231257,
      7746114.14307247
    ],
    [
      326870.43319607,
      7747389.6179665
    ]
  ]
],
"type": "MultiLineString"
},
"geometry_name": "the_geom",
"id": "ana_snirh_adutora_es_epsg_31984.5",
"properties": {
  "ADUTORA": "SIN - Marechal Floriano - Domingos Martins",
  "ESTADO": "ES",
  "SITUAA": "Sistema Existente",
  "fid": 5
},
"type": "Feature"
},
{
  "geometry": {
    "coordinates": [
      [
        [
          315745.0426298,
          7693972.43110099
        ],
        [
          317112.89527998,
          7694443.82457751
        ],
        [
          319982.18544051,
          7695126.94967117
        ],
        [
          320892.57843961,
          7695593.09637359
        ],
        [
          324085.67543483,
          7696604.89066975
        ],
        [
          325189.05148492,
          7697398.87319613
        ],
        [
          326423.83914094,
          7698128.81609286
        ],
        [
          328573.50590558,
          7698933.34381192
        ],
        [
          329293.39291815,
          7698875.47281758
        ],
        [
          331135.38030217,
          7697785.73065217
        ],
        [
          331859.12108824,
          7697336.63409638
        ]
      ]
    ]
  },
  [
    [
      318603.61459719,
```

```

        7701697.36307036
      ],
      [
        324085.67543483,
        7696604.89066975
      ]
    ],
    "type": "MultiLineString"
  },
  "geometry_name": "the_geom",
  "id": "ana_snirh_adutora_es_epsg_31984.6",
  "properties": {
    "ADUTORA": "SIN - Anchieta - Pi\u00c3\u00bama",
    "ESTADO": "ES",
    "SITUAA": "Sistema Existente",
    "fid": 6
  },
  "type": "Feature"
},
{
  "geometry": {
    "coordinates": [
      [
        [
          309204.00656975,
          7676688.39448986
        ],
        [
          309387.37563297,
          7675561.49722323
        ],
        [
          309880.85201664,
          7673798.24818449
        ],
        [
          310468.75872039,
          7672036.07038097
        ]
      ]
    ],
    "type": "MultiLineString"
  },
  "geometry_name": "the_geom",
  "id": "ana_snirh_adutora_es_epsg_31984.7",
  "properties": {
    "ADUTORA": "SIN - Itapemirim - Marata\u00c3\u00adzes",
    "ESTADO": "ES",
    "SITUAA": "Sistema Existente",
    "fid": 7
  },
  "type": "Feature"
}
],
"numberMatched": 7,
"numberReturned": 7,
"timeStamp": "2026-07-10T05:19:58.269Z",
"totalFeatures": 7,
"type": "FeatureCollection"
}

```